

SODA SPRINGS AIRPORT (ALLEN H. TIGERT)

This report describes how your pavement maintenance management program was developed. This program was developed as part of the Network Pavement Management Program project sponsored by the Idaho Transportation Department, Division of Aeronautics. The information and data contained in this report ensures you are in compliance with the requirements of Federal Aviation Administration (FAA) Grant Assurance Number 11 which states that any airport requesting federal funds for pavement improvement projects must have implemented a pavement maintenance management program (PMMP).

DATA COLLECTION

To determine how your pavements were constructed and their age, a records review was conducted. Figure SS-1 shows the records review results. This figure shows pavement boundaries, dimensions, pavement layer types, thicknesses and dates of construction. Table SS-1, provided in Appendix 1, contains the up-to-date cross-section information for each pavement section. The most recent construction date for each pavement can also be found in the Section Condition Report in Appendix 2. Figure SS-1, Table SS-1, and the information contained in Appendices 1 and 2 ensure that your airport complies with the “pavement inventory” requirement of FAA’s PMMP guidelines.

The pavements at your airport were divided into branches, sections and sample units in accordance with the methodology outlined in the current editions of FAA Advisory Circular AC:150/5380-6, *Guidelines and Procedures for Maintenance of Airport Pavements* and ASTM D5430, *Standard Test Method for Airport Condition Index Surveys*. The branches, sections and sample units established at your airport are shown in Figure SS-2. A Branch Condition Report showing all branches, their associated areas, and area-weighted condition is provided in Appendix 2. Additionally, the Appendix 2 Section Condition Report provides information that the Micro PAVER pavement management software uses to define each branch and section.

Using the branch, section and sample unit divisions established, a visual condition survey was conducted at Soda Springs Airport (Allen H. Tigert) on November 05, 2006. During the inspection pavement defects were identified and measured in accordance with the methodology outlined in FAA AC:150/5380-6 and ASTM D5430. Our inspection ensures your airport complies with the “detailed inspection” requirement of FAA’s PMMP guidelines. After collection, the data were entered into the Micro PAVER software for analysis. These data are reproduced in the Re-Inspection Report attached in Appendix 2. Photographs of typical distresses observed during the inspections are provided in Appendix 3.

Figure SS-1. Airport Layout, Pavement and Dimensions Cross-Sections.

Soda Springs Airport (Allen H. Tigert)





Figure SS-2. Pavement Branch, Section and Sample Unit Layout.
Soda Springs Airport (Allen H. Tigert)



The Micro PAVER database updated during this project ensures your airport complies with the “record keeping and information retrieval” requirements of FAA’s PMMP guidelines.


RESULTS

Using the data collected during the visual inspection, the Micro PAVER software calculated a Pavement Condition Index (PCI) for each pavement section inspected by averaging the PCIs for inspected sample units. Using each section’s PCI, a Pavement Condition Rating (PCR) was assigned. The PCIs and associated PCRs from this inspection are shown in Table SS-2. This table also contains projected PCIs for 2011 and 2016 based on pavement deterioration models developed by Micro PAVER using the inspection data from pavements in Idaho having the same surface types. The Branch Condition Report in Appendix 2 summarizes current pavement condition by branch while the Section Condition Report in Appendix 2 lists pavement condition by section. The current PCR is shown graphically in Figure SS-3.

Table SS-2. Present and Future Pavement Condition Indices.

Branch	Section	2006		2011		2016	
		PCI	PCR	PCI	PCR	PCI	PCR
A01SS	01	13	Very Poor	8	Failed	3	Failed
A01SS	02	3	Failed	0	Failed	0	Failed
A01SS	03	24	Very Poor	18	Very Poor	13	Very Poor
A01SS	04	7	Failed	2	Failed	0	Failed
A01SS	05	1	Failed	0	Failed	0	Failed
A02SS	01	30	Poor	23	Very Poor	17	Very Poor
A02SS	02	4	Failed	0	Failed	0	Failed
A02SS	03	50	Fair	40	Poor	32	Poor
A03SS	01	11	Very Poor	6	Failed	0	Failed
AFSS	01	100	Excellent	66	Good	64	Good
AHR34SS	01	24	Very Poor	18	Very Poor	13	Very Poor
AHR34SS	02	7	Failed	2	Failed	0	Failed
R13SS	01	32	Poor	5	Failed	0	Failed
R13SS	02	66	Good	45	Fair	43	Fair
R16SS	01	11	Very Poor	7	Failed	2	Failed
R16SS	02	36	Poor	31	Poor	26	Poor
T01SS	01	100	Excellent	86	Excellent	75	Very Good
T01SS	02	100	Excellent	86	Excellent	75	Very Good
T01SS	03	100	Excellent	86	Excellent	75	Very Good
T02SS	01	100	Excellent	86	Excellent	75	Very Good

Figure SS-3. Pavement Condition in 2006.
Soda Springs Airport (Allen H. Tigert)



Section PCIs at the airport range from a low of 1 (a PCR of “Failed”) to a high of 100 (a PCR of “Excellent”). The area-weighted average PCI for all airport pavements is 41, corresponding to an overall PCR of “Fair”. Figure SS-4 shows how much pavement area is associated with each Pavement Condition Rating category and also shows pavement condition distribution from the inspections conducted in 1996 and 1999. A graphical representation of the projected PCRs presented in Table SS-2 is shown in Figure SS-5.

The primary distresses observed during the inspection of asphalt concrete pavement were block cracking, weathering/raveling, alligator cracking, depression, longitudinal and transverse cracking, and patching with isolated occurrences of swelling and bleeding. The primary distresses observed during the inspection of portland cement concrete were joint seal damage and shattered slabs.

RECOMMENDATIONS


Data collected during the visual condition survey were used by the Micro PAVER software to generate the Network Maintenance Report contained in Appendix 4. This report identifies, for each pavement section, the recommended localized maintenance activities that should be completed to repair the defects observed during the visual inspection. The repair quantities identified in the report were extrapolated to cover the entire pavement section, based on the inspected sample units. If the repair activities identified are completed, the pavement deterioration rate will slow.

The localized maintenance activities to be applied are selected by the Micro PAVER software based on the Maintenance & Repair (M&R) policy established for the Idaho airport system. The report results indicate that, over the entire airport, the following quantities of localized maintenance are needed:


- 64,520 linear feet of asphalt concrete crack sealing.
- 2,800 square feet of asphalt concrete shallow patching.
- 50 square feet of asphalt concrete leveling.
- 44,650 square feet of asphalt concrete deep patching.
- 200 linear feet of portland cement concrete crack sealing.
- 120 linear feet of portland cement concrete joint sealing.

The Micro PAVER software also can identify and schedule recommended global (applied over an entire section) maintenance activities such as fog seals, slurry seals and other surface treatments, as well as major rehabilitation activities such as asphalt concrete overlays and complete reconstruction. To determine when a pavement section requires global maintenance or rehabilitation, Micro PAVER uses the pavement deterioration models developed during this project. These models are used to estimate future pavement condition and to schedule global maintenance and rehabilitation recommendations based on a trigger PCI.


**Figure SS-4. Distribution of Pavement Condition
Soda Springs Airport (Allen H. Tigert)**



Predicted Condition in 2011.



Predicted Condition in 2016.



Drawing Date: November 2006



PAVEMENT CONSULTANTS INC.


Figure SS-5. Future Pavement Condition.

During this project a 5-year program outlining recommended global maintenance and rehabilitation was developed. The program begins in 2007. These recommendations are presented in Table SS-3, which identifies the pavement section requiring rehabilitation, the year the action should be completed, the type of action, and an associated cost. This information is also presented graphically in Figure SS-6.

Table SS-3. Five-Year Global Maintenance and Rehabilitation Plan.

Year	Branch	Section	Action	Area (sf)	Unit Cost (\$/sf)	Total Cost (\$)
2007	A01SS	01	Reconstruct with 3" AC, 6" Cr. Agg. Base	11,037	\$2.48	\$27,372
	A01SS	02	Reconstruct with 3" AC, 6" Cr. Agg. Base	26,230	\$2.48	\$65,050
	A01SS	03	Reconstruct with 3" AC, 6" Cr. Agg. Base	11,804	\$2.48	\$29,274
	A01SS	04	Reconstruct with 3" AC, 6" Cr. Agg. Base	11,058	\$2.48	\$27,424
	A01SS	05	Reconstruct with 3" AC, 6" Cr. Agg. Base	11,127	\$2.48	\$27,595
	A02SS	01	Reconstruct with 3" AC, 6" Cr. Agg. Base	16,388	\$2.48	\$40,642
	A02SS	02	Reconstruct with 3" AC, 6" Cr. Agg. Base	7,804	\$2.48	\$19,354
	A02SS	03	2" AC Overlay	13,148	\$1.00	\$13,148
	A03SS	01	Reconstruct with 3" AC, 6" Cr. Agg. Base	1,600	\$2.48	\$3,968
	AHR34SS	01	Reconstruct with 3" AC, 6" Cr. Agg. Base	3,094	\$2.48	\$7,673
	AHR34SS	02	Reconstruct with 3" AC, 6" Cr. Agg. Base	3,094	\$2.48	\$7,673
	R13SS	01	Reconstruct with 3" AC, 6" Cr. Agg. Base	13,500	\$2.48	\$33,480
	R13SS	02	2" AC Overlay	116,500	\$1.00	\$116,500
	R16SS	01	Reconstruct with 3" AC, 6" Cr. Agg. Base	15,000	\$2.48	\$37,200
	R16SS	02	Reconstruct with 3" AC, 6" Cr. Agg. Base	167,500	\$2.48	\$415,400
2007 Total						\$871,753
2010	T01SS	01	Fog Seal	1,940	\$0.15	\$291
	T01SS	02	Fog Seal	2,580	\$0.15	\$387
	T01SS	03	Fog Seal	970	\$0.15	\$146
	T02SS	01	Fog Seal	22,100	\$0.15	\$3,315
2010 Total						\$4,139
TOTAL						\$875,892

Figure SS-6. Five-Year Pavement Management Plan.
Soda Springs Airport (Allen H. Tigert)



If the global maintenance or rehabilitation activities recommended in Table SS-3 are not completed, the localized maintenance activities identified in the Network Maintenance Report (Appendix 4) for that section should be completed. Additionally, for those sections not listed in Table SS-3 as requiring global maintenance or rehabilitation, the localized maintenance activities outlined in the Network Maintenance Report should be completed. By completing the localized maintenance activities, pavement condition is improved, life is extended, deterioration is slowed and the length of time until major repair or rehabilitation is required is increased.

INSPECTION SCHEDULE

To comply with the inspection schedule requirement of FAA Grant Assurance Number 11, a detailed visual inspection should be conducted every three (3) years using the methodology in FAA AC:150/5380-6 and ASTM D5430. The next scheduled detailed visual inspection should take place during 2009.

In addition, as part of the FAA-mandated pavement maintenance management program, a drive-by inspection must be conducted monthly to detect unforeseen or abrupt changes in pavement condition that have occurred since the last monthly inspection. Additionally, any maintenance activities completed during the previous month should be noted. The results of each drive-by inspection should be recorded and kept on file for five (5) years.

This inspection can easily be accomplished by driving your airport and recording your observations on the "Monthly Drive-By Inspection Form" provided as Figure SS-7. Each drive-by inspection should note the date of the inspection, any change in pavement condition, and an indication of any maintenance performed since the last drive-by inspection. A copy of each drive-by inspection report should be sent to Mr. William P. Statham at the Idaho Division of Aeronautics, P.O. Box 7129, Boise, ID 83709.

RECORD KEEPING

As part of the FAA-mandated pavement maintenance management program, you must record and keep on file for a minimum of five (5) years, complete information about all detailed pavement inspections and maintenance performed. The types of distress, their locations, and remedial actions, scheduled or performed, must be documented. The minimum information to be recorded is:


- Inspection date
- Location of pavement distress
- Distress types observed
- Type of maintenance scheduled or performed
- Date maintenance was performed

It would be useful to maintain documentation as to the type of maintenance completed such as engineering reports, drawings and specifications.

Note that you may use any form or record keeping you deem appropriate so long as the information and records produced by the pavement survey can be retrieved as necessary for any reports required by the FAA.

This report fulfills FAA's record keeping requirements. Additionally, this report and any subsequent information compiled by you will form the basis of the next detailed inspection and evaluation.

Figure SS-7. Monthly Drive-By Inspection Form
Soda Springs Airport (Allen H. Tigert)



Inspection Date: _____

Inspected By: _____

Branch	Section	Maintenance Performed Since Last Inspection

Note any changed condition on drawing

Send a copy of the inspection report to:

Willaims P. Statham, Idaho Division of Aeronautics

P.O. Box 7129 / Boise, ID 83707-1129

Fax: (208) 334-8789

TABLE SS-1. PAVEMENT HISTORY REPORT

Airport Name: Soda Springs

Page: 1 of: 3

Date Prepared: 1-Feb-07

Feature No.	Soil Class	Subgrade Class	CBR	Subgrade Prep.	Frost Course	Subbase Course	Base Course	Surface Course	Overlay Course	Surface Treatment	Crack Seal
	Project Number			Date							
R13SS 1							Unknown	Double BST			
	Unknown			1993							
R13SS 2							Unknown	Double BST			
	Unknown			1993							
R16SS 1						Pit Run Gravel	Unknown	2.4" AC Plant Mix			
	IAAP (?)			1969							
R16SS 1										Slurry Seal P-626	Crack Seal P-605
	IAAP-02			1983							
R16SS 1									2" AC Recycled	Fog Seal	
	Unknown			1992							
R16SS 2						Pit Run Gravel	Unknown	2.4" AC Plant Mix			
	IAAP (?)			1969							
R16SS 2										Slurry Seal P-626	Crack Seal P-605
	IAAP-02			1983							
R16SS 2									2" AC Recycled	Fog Seal	
	Unknown			1992							
T01SS 1						Unknown	Unknown	3" AC			
	Unknown			2006							
T01SS 2						Unknown	Unknown	3" AC			
	Unknown			2006							
T01SS 3						Unknown	Unknown	3" AC			
	Unknown			2006							
T02SS 1						Unknown	Unknown	3" AC			
	Unknown			2006							
A01SS 1						Pit Run Gravel	Unknown	2.4" AC Plant Mix			
	IAAP (?)			1969							
A01SS 2						Pit Run Gravel	Unknown	2.4" AC Plant Mix			
	IAAP (?)			1969							
A01SS 2										Slurry Seal P-626	Crack Seal P-605
	IAAP-02			1983							

TABLE SS-1. PAVEMENT HISTORY REPORT

Airport Name: Soda Springs

Page: 2 of: 3

Date Prepared: 1-Feb-07

Feature No.	Soil Class	Subgrade Class	CBR	Subgrade Prep.	Frost Course	Subbase Course	Base Course	Surface Course	Overlay Course	Surface Treatment	Crack Seal
	Project Number			Date							
A01SS 3						Pit Run Gravel	Unknown	2.4" AC Plant Mix			
	IAAP (?)			1969							
A01SS 3										Slurry Seal P-626	Crack Seal P-605
	IAAP-02			1983							
A01SS 3										Fog Seal	
	Unknown			1991							
A01SS 4						Pit Run Gravel	Unknown	2.4" AC Plant Mix			
	IAAP (?)			1969							
A01SS 4										Slurry Seal P-626	Crack Seal P-605
	IAAP-02			1983							
A01SS 5						Pit Run Gravel	Unknown	2.4" AC Plant Mix			
	IAAP (?)			1969							
A01SS 5										Slurry Seal P-626	Crack Seal P-605
	IAAP-02			1983							
A01SS 5										Fog Seal	
	Unknown			1991							
A02SS 1							Unknown	2" AC			
	Unknown			Unknown							
A02SS 2							Unknown	Unknown			
	Unknown			Unknown							
A02SS 3							Unknown	Unknown			
	Unknown			Unknown							
A03SS 1						Unknown	Unknown	PCC			
	Unknown			Unknown							
AFSS 1						Unknown	Unknown	PCC			
	Unknown			2006							
AHR34SS 1						12"	Unknown	2.4" AC Plant Mix			
	IAAP (?)			1969							
AHR34SS 1										Slurry Seal P-626	
	IAAP-02			1983							

TABLE SS-1. PAVEMENT HISTORY REPORT

Airport Name: Soda Springs

Page: 3 of: 3

Date Prepared: 1-Feb-07

Feature No.	Soil Class	Subgrade Class	CBR	Subgrade Prep.	Frost Course	Subbase Course	Base Course	Surface Course	Overlay Course	Surface Treatment	Crack Seal
	Project Number			Date							
AHR34SS						12"	Unknown	2.4" AC Plant Mix			
2	IAAP (?)			1969							
AHR34SS										Slurry Seal P-626	
2	IAAP-02			1983							

Date: 5 /18/2007

Branch Condition Report

1 of 2

Pavement Database: NetworkID: SODA

Branch ID	Number of Sections	Sum Section Length (Ft)	Avg Section Width (Ft)	True Area (SqFt)	Use	Average PCI	PCI Standard Deviation	Weighted Average PCI
A01SS (Apron 01 Soda Springs)	5	948.00	75.40	71,256.00	APRON	9.60	8.28	8.34
A02SS (Apron 02 Soda Springs)	3	412.00	92.00	37,340.00	APRON	28.00	18.83	31.61
A03SS (Apron 03 Soda Springs)	1	40.00	40.00	1,600.00	APRON	11.00	0.00	11.00
AFSS (Fuel Pad Soda Springs)	1	20.00	20.00	400.00	APRON	100.00	0.00	100.00
AHR34SS (H Apr 34 Soda Springs)	2	300.00	30.00	6,188.00	APRON	15.50	8.50	15.50
R13SS (Rwy 13/31 Soda Springs)	2	2,600.00	50.00	130,000.00	RUNWAY	49.00	17.00	62.47
R16SS (Rwy 16/34 Soda Springs)	2	3,650.00	50.00	182,500.00	RUNWAY	23.50	12.50	33.95
T01SS (Taxiway 01 Soda Springs)	3	323.00	16.67	5,490.00	TAXIWAY	100.00	0.00	100.00
T02SS (Taxiway 02 Soda Springs)	1	486.00	50.00	22,100.00	TAXIWAY	100.00	0.00	100.00

Date: 5 /18/2007

Branch Condition Report

2 of 2

Pavement Database:

Use Category	Number of Sections	Total Area (SqFt)	Arithmetic Average PCI	Average PCI STD.	Weighted Average PCI
APRON	12	116,784.00	22.83	26.94	16.51
RUNWAY	4	312,500.00	36.25	19.63	45.81
TAXIWAY	4	27,590.00	100.00	0.00	100.00
All	20	456,874.00	40.95	37.57	41.59

Date: 5 /18/2007

Section Condition Report

1 of 2

Pavement Database: NetworkID: SODA

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
A01SS (Apron 01 Soda Springs)	01	08/03/1969	AC	APRON	P	0	11,037.00	11/05/2006	37	13.00
A01SS (Apron 01 Soda Springs)	02	08/02/1969	AC	APRON	P	0	26,230.00	11/05/2006	37	3.00
A01SS (Apron 01 Soda Springs)	03	08/03/1969	AC	APRON	P	0	11,804.00	11/05/2006	37	24.00
A01SS (Apron 01 Soda Springs)	04	08/03/1969	AC	APRON	P	0	11,058.00	11/05/2006	37	7.00
A01SS (Apron 01 Soda Springs)	05	08/03/1969	AC	APRON	P	0	11,127.00	11/05/2006	37	1.00
A02SS (Apron 02 Soda Springs)	01	08/01/1969	AC	APRON	P	0	16,388.00	11/05/2006	37	30.00
A02SS (Apron 02 Soda Springs)	02	08/01/1969	AC	APRON	P	0	7,804.00	11/05/2006	37	4.00
A02SS (Apron 02 Soda Springs)	03	08/01/1969	AC	APRON	P	0	13,148.00	11/05/2006	37	50.00
A03SS (Apron 03 Soda Springs)	01	08/01/1969	PCC	APRON	P	0	1,600.00	11/05/2006	37	11.00
AFSS (Fuel Pad Soda Springs)	01	01/01/2006	PCC	APRON	P	0	400.00	11/05/2006	0	100.00
AHR34SS (H Apr 34 Soda Springs)	01	09/03/1969	AC	APRON	P	0	3,094.00	11/05/2006	37	24.00
AHR34SS (H Apr 34 Soda Springs)	02	09/03/1969	AC	APRON	P	0	3,094.00	11/05/2006	37	7.00
R13SS (Rwy 13/31 Soda Springs)	01	08/01/1993	X	RUNWAY	S	0	13,500.00	11/05/2006	13	32.00
R13SS (Rwy 13/31 Soda Springs)	02	08/01/1993	X	RUNWAY	S	0	116,500.00	11/04/2006	13	66.00
R16SS (Rwy 16/34 Soda Springs)	01	08/01/1992	AC	RUNWAY	P	0	15,000.00	11/05/2006	14	11.00
R16SS (Rwy 16/34 Soda Springs)	02	08/01/1992	AC	RUNWAY	P	0	167,500.00	11/05/2006	14	36.00
T01SS (Taxiway 01 Soda Springs)	01	01/01/2006	AC	TAXIWAY	P	0	1,940.00	11/05/2006	0	100.00
T01SS (Taxiway 01 Soda Springs)	02	01/01/2006	AC	TAXIWAY	P	0	2,580.00	11/05/2006	0	100.00
T01SS (Taxiway 01 Soda Springs)	03	01/01/2006	AC	TAXIWAY	P	0	970.00	11/05/2006	0	100.00
T02SS (Taxiway 02 Soda Springs)	01	02/01/2006	AC	TAXIWAY	P	0	22,100.00	11/05/2006	0	100.00

Date: 5 /18/2007

Section Condition Report

2 of 2

Pavement Database:

Age Category	Average Age At Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	PCI Standard Deviation	Weighted Average PCI
0-02	0.00	27,990.00	5	100.00	0.00	100.00
11-15	13.50	312,500.00	4	36.25	19.63	45.81
36-40	37.00	116,384.00	11	15.82	14.19	16.22
All	23.05	456,874.00	20	40.95	37.57	41.59

Re-inspection Report

idaho2006

Report Generated Date: 5/18/2007

Site Name:

Network: SODA Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)

Branch: A01SS Name: Apron 01 Soda Springs Use: APRON Area: 71,256.00SqFt

Section: 01 of 5 From: Runway 16 End To: Taxiway 02 Last Const.: 8/3/1969
Surface: AC Family: Idaho AC Aprons Zone: U78 Category: 5 Rank: P
Area: 11,037.00SqFt Length: 303.00Ft Width: 36.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 11/5/2006 Total Samples: 3 Surveyed: 3
Conditions: PCI:13.00 |

Sample Number: 01	Type: R	Area:	1,094.00SqFt	PCI = 18
41 ALLIGATOR CRACKING		M	300.00 SqFt	
45 DEPRESSION		L	10.00 SqFt	
43 BLOCK CRACKING		M	793.98 SqFt	

Sample Number: 02	Type: R	Area:	5,400.00SqFt	PCI = 21
41 ALLIGATOR CRACKING		M	1,199.99 SqFt	
43 BLOCK CRACKING		M	4,199.94 SqFt	

Sample Number: 03	Type: R	Area:	4,544.00SqFt	PCI = 1
41 ALLIGATOR CRACKING		M	550.00 SqFt	
43 BLOCK CRACKING		M	3,493.94 SqFt	
41 ALLIGATOR CRACKING		H	500.00 SqFt	
52 WEATHERING/RAVELING		H	300.00 SqFt	

Re-inspection Report

idaho2006

Report Generated Date: 5/18/2007

Site Name:

Network: SODA Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)

Branch: A01SS Name: Apron 01 Soda Springs Use: APRON Area: 71,256.00SqFt

Section: 02 of 5 From: Section 01 To: Taxiway 01 Last Const.: 8/2/1969
Surface: AC Family: Idaho AC Aprons Zone: U78 Category: 5 Rank: P
Area: 26,230.00SqFt Length: 217.00Ft Width: 109.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 11/5/2006 Total Samples: 6 Surveyed: 4
Conditions: PCI:3.00 |

Sample Number: 01 Type: R Area: 1,643.00SqFt PCI = 0
41 ALLIGATOR CRACKING M 500.00 SqFt
41 ALLIGATOR CRACKING H 485.00 SqFt
52 WEATHERING/RAVELING M 657.98 SqFt

Sample Number: 02 Type: R Area: 5,000.00SqFt PCI = 5
41 ALLIGATOR CRACKING M 1,499.99 SqFt
41 ALLIGATOR CRACKING H 500.00 SqFt
52 WEATHERING/RAVELING M 999.99 SqFt

Sample Number: 03 Type: R Area: 5,000.00SqFt PCI = 3
41 ALLIGATOR CRACKING M 3,499.97 SqFt
41 ALLIGATOR CRACKING H 400.00 SqFt
43 BLOCK CRACKING M 1,099.99 SqFt

Sample Number: 05 Type: R Area: 4,603.00SqFt PCI = 0
41 ALLIGATOR CRACKING M 500.00 SqFt
41 ALLIGATOR CRACKING H 1,999.98 SqFt
43 BLOCK CRACKING M 999.99 SqFt

Re-inspection Report

idaho2006

Report Generated Date: 5/18/2007

Site Name:

Network: SODA Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)

Branch: A01SS Name: Apron 01 Soda Springs Use: APRON Area: 71,256.00SqFt

Section: 03 of 5 From: Taxiway 02 To: Apron 02 Last Const.: 8/3/1969
Surface: AC Family: Idaho AC Aprons Zone: U78 Category: 5 Rank: P
Area: 11,804.00SqFt Length: 122.00Ft Width: 95.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 11/5/2006 Total Samples: 3 Surveyed: 3
Conditions: PCI: 24.00 |

Sample Number: 01 Type: R Area: 2,303.00SqFt PCI = 25
41 ALLIGATOR CRACKING M 300.00 SqFt
48 LONGITUDINAL/TRANSVERSE CRACKING M 100.03 Ft
50 PATCHING L 106.00 SqFt
52 WEATHERING/RAVELING L 2,302.98 SqFt

Sample Number: 03 Type: R Area: 4,750.00SqFt PCI = 33
41 ALLIGATOR CRACKING M 271.00 SqFt
48 LONGITUDINAL/TRANSVERSE CRACKING M 370.09 Ft
52 WEATHERING/RAVELING L 4,749.96 SqFt

Sample Number: 03 Type: R Area: 4,750.00SqFt PCI = 13
41 ALLIGATOR CRACKING M 2,004.98 SqFt
43 BLOCK CRACKING M 999.99 SqFt
48 LONGITUDINAL/TRANSVERSE CRACKING L 35.01 Ft
48 LONGITUDINAL/TRANSVERSE CRACKING M 80.02 Ft
52 WEATHERING/RAVELING L 4,749.96 SqFt

Re-inspection Report

idaho2006
Report Generated Date: 5/18/2007
Site Name:

Network:	SODA	Name:	SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)			
Branch:	A01SS	Name:	Apron 01 Soda Springs	Use:	APRON	Area: 71,256.00SqFt
Section:	04	of	5	From:	Taxiway 01	To: Taxiway 02
Surface:	AC	Family:	Idaho AC Aprons	Zone:	U78	Category: 5
Area:	11,058.00SqFt	Length:	114.00Ft	Width:	97.00Ft	Rank: P
Shoulder:	Street Type:	Grade:	0.00	Lanes:	0	Last Const.: 8/3/1969
Section Comments:						
Last Insp. Date	11/5/2006	Total Samples:	2	Surveyed:	2	
Conditions: PCI:7.00						

Sample Number:	01	Type:	R	Area:	5,358.00SqFt	PCI = 14
41	ALLIGATOR CRACKING			M	1,999.98 SqFt	
43	BLOCK CRACKING			M	2,857.98 SqFt	
45	DEPRESSION			L	400.00 SqFt	
52	WEATHERING/RAVELING			L	5,357.96 SqFt	

Sample Number:	02	Type:	R	Area:	5,700.00SqFt	PCI = 0
41	ALLIGATOR CRACKING			M	2,299.98 SqFt	
43	BLOCK CRACKING			M	2,699.98 SqFt	
41	ALLIGATOR CRACKING			H	699.99 SqFt	
45	DEPRESSION			L	500.00 SqFt	
52	WEATHERING/RAVELING			L	5,699.95 SqFt	

Re-inspection Report

idaho2006

Report Generated Date: 5/18/2007

Site Name:

Network: SODA Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)

Branch: A01SS Name: Apron 01 Soda Springs Use: APRON Area: 71,256.00SqFt

Section: 05 of 5 From: Runway 13 To: Runway 16 Last Const.: 8/3/1969
Surface: AC Family: Idaho AC Aprons Zone: U78 Category: 5 Rank: P
Area: 11,127.00SqFt Length: 192.00Ft Width: 40.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 11/5/2006 Total Samples: 3 Surveyed: 3
Conditions: PCI: 1.00 |

Sample Number: 01 Type: R Area: 4,460.00SqFt PCI = 3
41 ALLIGATOR CRACKING M 1,199.99 SqFt
41 ALLIGATOR CRACKING H 659.99 SqFt
43 BLOCK CRACKING M 600.00 SqFt
45 DEPRESSION L 100.00 SqFt
52 WEATHERING/RAVELING H 100.00 SqFt
52 WEATHERING/RAVELING L 4,359.96 SqFt
43 BLOCK CRACKING L 1,999.98 SqFt

Sample Number: 02 Type: R Area: 3,300.00SqFt PCI = 0
43 BLOCK CRACKING L 999.99 SqFt
41 ALLIGATOR CRACKING M 999.99 SqFt
41 ALLIGATOR CRACKING H 400.00 SqFt
43 BLOCK CRACKING M 899.99 SqFt
45 DEPRESSION L 300.00 SqFt
52 WEATHERING/RAVELING H 300.00 SqFt
52 WEATHERING/RAVELING L 2,999.98 SqFt

Sample Number: 03 Type: R Area: 3,366.00SqFt PCI = 0
43 BLOCK CRACKING L 999.99 SqFt
41 ALLIGATOR CRACKING M 999.99 SqFt
41 ALLIGATOR CRACKING H 366.00 SqFt
43 BLOCK CRACKING M 999.99 SqFt
45 DEPRESSION L 500.00 SqFt
52 WEATHERING/RAVELING H 500.00 SqFt
52 WEATHERING/RAVELING L 2,865.98 SqFt

Re-inspection Report

idaho2006
Report Generated Date: 5/18/2007
Site Name:

Network:	SODA	Name:	SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)			
Branch:	A02SS	Name:	Apron 02 Soda Springs	Use:	APRON	Area: 37,340.00SqFt
Section:	01	of	3	From:	Section 02	To: Hangars
Surface:	AC	Family:	Idaho AC Aprons	Zone:	U78	Category: 5
Area:	16,388.00SqFt	Length:	168.00Ft	Width:	100.00Ft	Rank: P
Shoulder:	Street Type:	Grade:	0.00	Lanes:	0	Last Const.: 8/1/1969
Section Comments:						
Last Insp. Date	11/5/2006	Total Samples:	4	Surveyed:	3	
Conditions: PCI:30.00						

Sample Number:	01	Type:	R	Area:	5,000.00SqFt	PCI = 28
41	ALLIGATOR CRACKING	L		500.00	SqFt	
41	ALLIGATOR CRACKING	M		200.00	SqFt	
43	BLOCK CRACKING	L		999.99	SqFt	
43	BLOCK CRACKING	M		500.00	SqFt	

Sample Number:	02	Type:	R	Area:	5,000.00SqFt	PCI = 28
41	ALLIGATOR CRACKING	L		500.00	SqFt	
41	ALLIGATOR CRACKING	M		200.00	SqFt	
43	BLOCK CRACKING	L		999.99	SqFt	
43	BLOCK CRACKING	M		500.00	SqFt	

Sample Number:	03	Type:	R	Area:	3,638.00SqFt	PCI = 34
41	ALLIGATOR CRACKING	L		500.00	SqFt	
41	ALLIGATOR CRACKING	M		50.00	SqFt	
43	BLOCK CRACKING	L		799.99	SqFt	
43	BLOCK CRACKING	M		50.00	SqFt	

Re-inspection Report

idaho2006
Report Generated Date: 5/18/2007
Site Name:

Network:	SODA	Name:	SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)			
Branch:	A02SS	Name:	Apron 02 Soda Springs	Use:	APRON	Area: 37,340.00SqFt
Section:	02	of	3	From:	Section 01	To: Section 03
Surface:	AC	Family:	Idaho AC Aprons	Zone:	U78	Category: 5
Area:	7,804.00SqFt	Length:	127.00Ft	Width:	66.00Ft	Rank: P
Shoulder:	Street Type:	Grade:	0.00	Lanes:	0	Last Const.: 8/1/1969
Section Comments:						
Last Insp. Date	11/5/2006	Total Samples:	2	Surveyed:	2	
Conditions: PCI:4.00						

Sample Number:	01	Type:	R	Area:	4,504.00SqFt	PCI = 6
41	ALLIGATOR CRACKING			M	999.99 SqFt	
41	ALLIGATOR CRACKING			H	252.00 SqFt	
43	BLOCK CRACKING			L	1,899.98 SqFt	
43	BLOCK CRACKING			H	300.00 SqFt	

Sample Number:	02	Type:	R	Area:	3,300.00SqFt	PCI = 1
41	ALLIGATOR CRACKING			L	500.00 SqFt	
41	ALLIGATOR CRACKING			M	999.99 SqFt	
41	ALLIGATOR CRACKING			H	150.00 SqFt	
43	BLOCK CRACKING			L	999.99 SqFt	
43	BLOCK CRACKING			H	649.99 SqFt	
50	PATCHING			L	180.00 SqFt	

Re-inspection Report

idaho2006

Report Generated Date: 5/18/2007

Site Name:

Network: SODA Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)

Branch: A02SS Name: Apron 02 Soda Springs Use: APRON Area: 37,340.00SqFt

Section: 03 of 3 From: Section 02 To: Apron 01 Last Const.: 8/1/1969
Surface: AC Family: Idaho AC Aprons Zone: Category: Rank: P
Area: 13,148.00SqFt Length: 117.00Ft Width: 110.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 11/5/2006 Total Samples: 3 Surveyed: 3
Conditions: PCI: 50.00 |

Sample Number: 01 Type: R Area: 2,148.00SqFt PCI = 53
43 BLOCK CRACKING L 1,099.99 SqFt
43 BLOCK CRACKING M 1,047.99 SqFt

Sample Number: 02 Type: R Area: 5,500.00SqFt PCI = 50
43 BLOCK CRACKING L 2,749.98 SqFt
43 BLOCK CRACKING M 2,749.98 SqFt
50 PATCHING L 51.00 SqFt

Sample Number: 03 Type: R Area: 5,500.00SqFt PCI = 48
43 BLOCK CRACKING L 2,599.98 SqFt
43 BLOCK CRACKING M 2,899.98 SqFt
50 PATCHING L 461.00 SqFt

Re-inspection Report

idaho2006
Report Generated Date: 5/18/2007
Site Name:

Network:	SODA	Name:	SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)			
Branch:	A03SS	Name:	Apron 03 Soda Springs	Use:	APRON	Area: 1,600.00SqFt
Section:	01	of	1	From:	Apron 01	Last Const.: 8/1/1969
Surface:	PCC	Family:	Idaho PCC Aprons	Zone:	Category:	Rank: P
Area:	1,600.00SqFt	Length:	40.00Ft	Width:	40.00Ft	
Shoulder:	Street Type:	Grade:	0.00	Lanes:	0	
Section Comments:						

Last Insp. Date11/5/2006 Total Samples: 1 Surveyed: 1
Conditions: PCI:11.00 |

Sample Number:	01	Type:	R	Area:	6.00Count	PCI = 11
65	JOINT SEAL DAMAGE			H	6.00 Count	
72	SHATTERED SLAB			M	6.00 Count	

idaho2006

Site Name:

Network: SODA		Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)			
Branch: AFSS		Name: Fuel Pad Soda Springs		Use: APRON	Area: 400.00SqFt
Section: 01	of 1	From: Apron 01		To: Taxiway 01	Last Const.: 1/1/2006
Surface: PCC	Family: Idaho PCC Aprons		Zone:	Category:	Rank: P
Area: 400.00SqFt	Length: 20.00Ft		Width: 20.00Ft		
Shoulder:	Street Type:	Grade: 0.00	Lanes: 0		
Section Comments:					
Last Insp. Date: 11/5/2006		Total Samples: 1	Surveyed: 1		
Conditions: PCI: 100.00					
Sample Number: 01		Type: R	Area: 1.00	Count	PCI = 100
<NO DISTRESSES>					

Re-inspection Report

idaho2006
Report Generated Date: 5/18/2007
Site Name:

Network:	SODA	Name:	SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)			
Branch:	AHR34SS	Name:	H Apr 34 Soda Springs	Use:	APRON	Area: 6,188.00SqFt
Section:	01	of	2	From:	Runway 34 End	To: West End
Surface:	AC	Family:	Idaho AC Aprons	Zone:	U78	Category: 5
Area:	3,094.00SqFt	Length:	150.00Ft	Width:	30.00Ft	Rank: P
Shoulder:	Street Type:	Grade:	0.00	Lanes:	0	Last Const.: 9/3/1969
Section Comments:						

Last Insp. Date11/5/2006 Total Samples: 1 Surveyed: 1
Conditions: PCI:24.00 |

Sample Number:	01	Type:	R	Area:	3,094.00SqFt	PCI = 24
43	BLOCK CRACKING			M	1,546.99 SqFt	
43	BLOCK CRACKING			H	1,546.99 SqFt	
52	WEATHERING/RAVELING			M	200.00 SqFt	

Re-inspection Report

idaho2006
Report Generated Date: 5/18/2007
Site Name:

Network:	SODA	Name:	SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)			
Branch:	AHR34SS	Name:	H Apr 34 Soda Springs	Use:	APRON	Area: 6,188.00SqFt
Section:	02	of	2	From:	Runway 34 End	To: East End
Surface:	AC	Family:	Idaho AC Aprons	Zone:	U78	Category: 5
Area:	3,094.00SqFt	Length:	150.00Ft	Width:	30.00Ft	Rank: P
Shoulder:	Street Type:	Grade:	0.00	Lanes:	0	Last Const.: 9/3/1969
Section Comments:						

Last Insp. Date11/5/2006 Total Samples: 1 Surveyed: 1
Conditions: PCI:7.00 |

Sample Number:	01	Type:	R	Area:	3,094.00SqFt	PCI = 7
41	ALLIGATOR CRACKING	M		242.00	SqFt	
43	BLOCK CRACKING	M		1,546.99	SqFt	
43	BLOCK CRACKING	H		1,546.98	SqFt	
52	WEATHERING/RAVELING	M		576.00	SqFt	

Re-inspection Report

idaho2006

Report Generated Date: 5/18/2007

Site Name:

Network: SODA Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)

Branch: R13SS Name: Rwy 13/31 Soda Springs Use: RUNWAY Area: 130,000.00SqFt

Section: 01 of 2 From: Section 02 To: Apron 01 Last Const.: 8/1/1993
Surface: X Family: Idaho X Runways Zone: U78 Category: 5 Rank: s
Area: 13,500.00SqFt Length: 270.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 11/5/2006 Total Samples: 3 Surveyed: 3
Conditions: PCI:32.00 |

Sample Number: 01 Type: R Area: 5,000.00SqFt PCI = 35
45 DEPRESSION M 500.00 SqFt
52 WEATHERING/RAVELING H 600.00 SqFt

Sample Number: 02 Type: R Area: 5,000.00SqFt PCI = 26
41 ALLIGATOR CRACKING M 140.00 SqFt
45 DEPRESSION L 400.00 SqFt
48 LONGITUDINAL/TRANSVERSE CRACKING M 40.01 Ft
52 WEATHERING/RAVELING H 500.00 SqFt

Sample Number: 03 Type: R Area: 3,500.00SqFt PCI = 36
41 ALLIGATOR CRACKING M 60.00 SqFt
48 LONGITUDINAL/TRANSVERSE CRACKING M 90.02 Ft
52 WEATHERING/RAVELING H 300.00 SqFt

Re-inspection Report

idaho2006

Report Generated Date: 5/18/2007

Site Name:

Network: SODA Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)

Branch: R13SS Name: Rwy 13/31 Soda Springs Use: RUNWAY Area: 130,000.00SqFt

Section: 02 of 2 From: Runway 31 End To: Section 01 Last Const.: 8/1/1993
Surface: X Family: Idaho X Runways Zone: U78 Category: 5 Rank: s
Area: 116,500.00SqFt Length: 2,330.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 11/4/2006 Total Samples: 23 Surveyed: 5
Conditions: PCI:66.00 |

Sample Number: 01 Type: R Area: 5,000.00SqFt PCI = 75
48 LONGITUDINAL/TRANSVERSE CRACKING M 57.01 Ft
52 WEATHERING/RAVELING L 2,499.98 SqFt

Sample Number: 06 Type: R Area: 5,000.00SqFt PCI = 70
45 DEPRESSION L 35.00 SqFt
48 LONGITUDINAL/TRANSVERSE CRACKING M 49.01 Ft
52 WEATHERING/RAVELING L 2,499.98 SqFt

Sample Number: 11 Type: R Area: 5,000.00SqFt PCI = 68
48 LONGITUDINAL/TRANSVERSE CRACKING M 29.01 Ft
52 WEATHERING/RAVELING L 2,499.98 SqFt
52 WEATHERING/RAVELING M 600.00 SqFt

Sample Number: 16 Type: R Area: 5,000.00SqFt PCI = 53
48 LONGITUDINAL/TRANSVERSE CRACKING L 27.01 Ft
42 BLEEDING N 50.00 SqFt
52 WEATHERING/RAVELING L 2,499.98 SqFt
52 WEATHERING/RAVELING M 1,399.99 SqFt

Sample Number: 23 Type: R Area: 6,500.00SqFt PCI = 64
52 WEATHERING/RAVELING L 3,249.97 SqFt
52 WEATHERING/RAVELING M 1,599.99 SqFt

Re-inspection Report

idaho2006

Report Generated Date: 5/18/2007

Site Name:

Network: SODA Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)

Branch: R16SS Name: Rwy 16/34 Soda Springs Use: RUNWAY Area: 182,500.00SqFt

Section: 01 of 2 From: Runway 16 End To: Section 02 Last Const.: 8/1/1992
Surface: AC Family: Idaho AC Runways Zone: U78 Category: 5 Rank: P
Area: 15,000.00SqFt Length: 300.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 11/5/2006 Total Samples: 3 Surveyed: 3
Conditions: PCI: 11.00 |

Sample Number: 01 Type: R Area: 5,000.00SqFt PCI = 6
41 ALLIGATOR CRACKING M 300.00 SqFt
41 ALLIGATOR CRACKING H 300.00 SqFt
43 BLOCK CRACKING M 3,799.94 SqFt
45 DEPRESSION H 25.00 SqFt
52 WEATHERING/RAVELING L 3,799.94 SqFt

Sample Number: 02 Type: R Area: 5,000.00SqFt PCI = 14
41 ALLIGATOR CRACKING M 200.00 SqFt
45 DEPRESSION M 15.00 SqFt
43 BLOCK CRACKING H 3,799.97 SqFt
52 WEATHERING/RAVELING L 3,799.94 SqFt

Sample Number: 03 Type: R Area: 5,000.00SqFt PCI = 11
41 ALLIGATOR CRACKING M 150.00 SqFt
43 BLOCK CRACKING H 3,799.97 SqFt
52 WEATHERING/RAVELING L 3,799.94 SqFt
52 WEATHERING/RAVELING H 200.00 SqFt

Re-inspection Report

idaho2006

Report Generated Date: 5/18/2007

Site Name:

Network: SODA Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)

Branch: R16SS Name: Rwy 16/34 Soda Springs Use: RUNWAY Area: 182,500.00SqFt

Section: 02 of 2 From: Runway 34 End To: Section 01 Last Const.: 8/1/1992
Surface: AC Family: Idaho AC Runways Zone: U78 Category: 5 Rank: P
Area: 167,500.00SqFt Length: 3,350.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 11/5/2006 Total Samples: 34 Surveyed: 6
Conditions: PCI:36.00 |

Sample Number: 01 Type: R Area: 5,000.00SqFt PCI = 33
43 BLOCK CRACKING M 4,999.96 SqFt
45 DEPRESSION M 110.00 SqFt
52 WEATHERING/RAVELING L 500.00 SqFt
56 SWELLING L 62.00 SqFt

Sample Number: 08 Type: R Area: 5,000.00SqFt PCI = 47
43 BLOCK CRACKING M 4,999.96 SqFt

Sample Number: 15 Type: R Area: 5,000.00SqFt PCI = 41
43 BLOCK CRACKING M 4,999.96 SqFt
41 ALLIGATOR CRACKING L 160.00 SqFt

Sample Number: 22 Type: R Area: 5,000.00SqFt PCI = 23
43 BLOCK CRACKING M 4,063.97 SqFt
41 ALLIGATOR CRACKING M 935.99 SqFt

Sample Number: 29 Type: R Area: 5,000.00SqFt PCI = 40
41 ALLIGATOR CRACKING M 79.00 SqFt
43 BLOCK CRACKING M 4,920.96 SqFt

Sample Number: 33 Type: R Area: 5,000.00SqFt PCI = 30
41 ALLIGATOR CRACKING M 316.00 SqFt
43 BLOCK CRACKING M 4,683.96 SqFt

idaho2006

Site Name:

Network: SODA		Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)			
Branch:	T01SS	Name: Taxiway 01 Soda Springs		Use: TAXIWAY	Area: 5,490.00SqFt
Section:	01	of 3	From: Apron 01	To: Taxiway 02	Last Const.: 1/1/2006
Surface:	AC	Family: Idaho AC Taxiways		Zone:	Category: Rank: P
Area:	1,940.00SqFt	Length: 97.00Ft		Width:	20.00Ft
Shoulder:	Street Type:		Grade: 0.00	Lanes: 0	
Section Comments:					
Last Insp. Date11/5/2006		Total Samples: 1		Surveyed: 1	
Conditions: PCI:100.00					
Sample Number: 01		Type: R	Area: 1,940.00SqFt	PCI = 100	
<NO DISTRESSES>					

idaho2006

Site Name:

Network: SODA		Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)			
Branch:	T01SS	Name: Taxiway 01 Soda Springs		Use: TAXIWAY	Area: 5,490.00SqFt
Section:	02	of 3	From: Apron Fuel	To: Apron 01	Last Const.: 1/1/2006
Surface:	AC	Family: Idaho AC Taxiways		Zone:	Category: Rank: P
Area:	2,580.00SqFt	Length:	129.00Ft	Width:	20.00Ft
Shoulder:	Street Type:		Grade: 0.00	Lanes: 0	
Section Comments:					
Last Insp. Date11/5/2006		Total Samples: 1	Surveyed: 1		
Conditions: PCI:100.00					
Sample Number: 01		Type: R	Area: 2,580.00SqFt	PCI = 100	
<NO DISTRESSES>					

idaho2006

Site Name:

Network: SODA		Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)			
Branch:	T01SS	Name: Taxiway 01 Soda Springs		Use: TAXIWAY	Area: 5,490.00SqFt
Section:	03	of 3	From: Apron 01	To: Taxiway 02	Last Const.: 1/1/2006
Surface:	AC	Family: Idaho AC Taxiways		Zone:	Category: Rank: P
Area:	970.00SqFt	Length: 97.00Ft		Width:	10.00Ft
Shoulder:	Street Type:		Grade: 0.00	Lanes: 0	
Section Comments:					
Last Insp. Date: 11/5/2006		Total Samples: 1		Surveyed: 1	
Conditions: PCI:100.00					
Sample Number: 01		Type: R	Area: 970.00SqFt	PCI = 100	
<NO DISTRESSES>					

Re-inspection Report

idaho2006

Report Generated Date: 5/18/2007

Site Name:

Network: SODA Name: SODA SPRINGS AIRPORT (ALLEN H. TIGERT FIELD)

Branch: T02SS Name: Taxiway 02 Soda Springs Use: TAXIWAY Area: 22,100.00SqFt

Section: 01 of 1 From: Apron 01 To: Apron 02 Last Const.: 2/1/2006
Surface: AC Family: Idaho AC Taxiways Zone: Category: Rank: P
Area: 22,100.00SqFt Length: 486.00Ft Width: 50.00Ft
Shoulder: Street Type: Grade: 0.00 Lanes: 0
Section Comments:

Last Insp. Date: 11/5/2006 Total Samples: 5 Surveyed: 3
Conditions: PCI:100.00 |

Sample Number: 01 Type: R Area: 4,000.00SqFt PCI = 100
<NO DISTRESSES>

Sample Number: 03 Type: R Area: 4,660.00SqFt PCI = 100
<NO DISTRESSES>

Sample Number: 05 Type: R Area: 5,000.00SqFt PCI = 100
<NO DISTRESSES>



Section: A01SS-01
Block Cracking
Alligator Cracking



Section: A01SS-02
Block Cracking



Section: A02SS-02
Block Cracking
Alligator Cracking



Section: A03SS-01
Shattered Slab
Joint Seal Damage



Section: R13SS-01
Weathering/ Raveling



Section: R13SS-02
Weathering/ Raveling



Section: R16SS-01
Block Cracking
Weathering/ Raveling



Section: T01SS-01
No Distress



Section: T01SS-03
No Distress



Section: AHR34SS-01
Block Cracking



Section: AHR34SS-02
Block Cracking

NETWORK MAINTENANCE REPORT

SODA SPRINGS AIRPORT (ALLEN H. TIGERT)

[illegible]

NETWORK MAINTENANCE REPORT - continued

SODA SPRINGS AIRPORT (ALLEN H. TIGERT)

[illegible]

NETWORK MAINTENANCE REPORT - continued

SODA SPRINGS AIRPORT (ALLEN H. TIGERT)

[illegible]

NETWORK MAINTENANCE REPORT - continued

SODA SPRINGS AIRPORT (ALLEN H. TIGERT)

[illegible]